

APPENDIX C – SITE PHOTOGRAPHS



Photograph 1: The existing building, access gate off Carr Street (yellow arrow) and vibcrete boundary wall is visible in this photograph. A ready-mix concrete batching plant previously operated from the site, which is hard serviced for most of its extent. The proponent does not intend to increase the extent of the hard surfaced areas.



Photograph 2: Facing the south-eastern boundary of the site.

APPENDIX J – SITE PHOTOGRAPHS

3



Photograph 3: Facing the northern corner of the site.